

**Menu**

HISTORY FILE MAP for year 2004

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

029.15:01-15:13: 12m realtime 1024bps data lost due to a long 1-way to 2-way transition at DSS34. TLP required 3 restarts to achieve lock. DR C103283 refers.

